

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:						
Company	Johnny Pappas Sr. Environmental Engineer					
OGM	Karl Houskeeper Environmental Scientist III					

Inspection Report

Permit Number:	C0070006
Inspection Type:	PARTIAL
Inspection Date:	Friday, April 09, 2004
Start Date/Time:	04/09/2004 9:00:00 AM
End Date/Time:	04/09/2004 3:00:00 PM
Last Inspection:	Friday, March 05, 2004

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, ~Temp 60 Deg F InspectionID Report Number: 233

Accepted by: pgrubaug

04/12/2004

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: 847 NW HWY 191, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

<u> </u>	+	A	
Cui	rent	Acreages	

9,084.00	Total Permitted		
213.40	Total Disturbed		
	Phase I		
•	Phase II		
	Phase III		

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ✓ State Surface County Loadout **✓** Fee Processing ☐ Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



Friday, April 09, 2004

Date

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Friday, April 09, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS, PERMIT CONDITION REQUIREMENT.

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark			
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		V		
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	V		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		V		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Friday, April 09, 2004

Page 3 of 3

2. Signs and Markers

The mine ID sign is in place at the contact point of the permit area with the public road access (Carbon County Road 290). The ID sign contains all the required information. All other markers and signs observed were in compliance with the approved MRP and the coal rules.

4.a Hydrologic Balance: Diversions

Most of the snow has melted at the mine site, however, there are several areas in the reclaimed diversions that still contain snow patches. Photographs of the No. 1 mine area and the Lions deck were taken during the inspection that show the reclaimed areas and isolated snow patches.

4.d Hydrologic Balance: Water Monitoring

Water monitoring information for the fourth quarter 2003 is uploaded in the EDI website. Water monitoring is current.